

	Type	Hits	Search Text	DBs
1	BRS	324	self\$calibrat\$5 and crystal and oscillator	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
2	BRS	15959 4	(adc a\$1d analog\$1digital) same memory	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
3	BRS	85	S1 and S2	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
4	BRS	56	S3 and temperature	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
5	BRS	297	331/44.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
6	BRS	25	331/44.ccls. and 331/158.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
7	BRS	5334	(pd or pfd or phase\$1comparator or phase\$1detector) same (adc a\$1d analog\$1digital)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
8	BRS	10041 75	crystal saw txco	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
9	BRS	1127	S7 and S8	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
10	BRS	397	S9 and memory	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
11	BRS	79	S10 and (crystal near oscillator)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
12	BRS	79	331/160.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
13	BRS	20	self\$calibrat\$5 near oscillat\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
14	BRS	1839	txco (temperature near compensat\$4 near crystal)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
15	BRS	0	S13 and S14	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
16	BRS	8	self\$calibrat\$5 and S14	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
17	BRS	56818	(phase\$1detect\$3 pfd pd phase\$1comparator phase\$1frequency) and (adc a\$1d analog\$1digital)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
18	BRS	11544 84	crystal saw surface\$1acoustic\$1wave piezoelectric piezo\$1electric	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
19	BRS	22910 53	memory ff register\$1 latch\$3 flip\$1flop	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
20	BRS	4906	S17 and S18 and S19	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
21	BRS	1908	S20 and oscillat\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
22	BRS	28740	S18 near oscillator	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
23	BRS	609	S21 and S22	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB

	Type	Hits	Search Text	DBs
24	BRS	63350 35	calibrat\$4 adjust\$4 chang\$3 test\$3	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
25	BRS	602	S23 and S24	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
26	BRS	5709	(phase\$1detect\$3 pfd pd phase\$1comparator phase\$1frequency)same (adc a\$1d analog\$1digital)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
27	BRS	119	S23 and S26	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
28	BRS	6489	S22 same S24	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
29	BRS	54	S27 and S28	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
30	BRS	47	(crystal saw surface\$1acoustic\$1wave piezoelectric piezo\$1electric) near oscillat\$3 near calibrat\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
31	BRS	45263	temperature near compensat\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
32	BRS	22	S30 and S31	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
33	BRS	0	S20 and S32	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB